

Site (Structure) : RPS

Country: PHILIPPINES

Reporting Year: 2007

Full Name: Radiation Protection Services

Location: Philippine Nuclear Research Institute
Diliman, Quezon City, Philippines

Description:

Official Website:

License Holder(s): not a licensed site, responsible organization is the Philippine Nuclear Research
Institute

Waste management facilities that are located at this site:

Site (Structure) : RPS

Country: PHILIPPINES

Reporting Year: 2007

Facility:	CWM&TF
Description:	Central Waste Management and Treatment Facility

Storage part of facility**CWM&TF**

The following shows storage status for waste classes and SRS.

Waste Class	Actual	Planned
VLLW	No	No
LLW	Yes	Yes
ILW	Yes	Yes
HLW	No	No

List SRS?	Yes
List UMMT?	No

Capacity:	
------------------	--

Types of Storage Units

Storage Unit Name	Type Name	Year Opened	Closed?	Full?	Modular?	Contains SRS?
Trench A	trench (lined)	1997	No	No	Yes	Yes
Trench B	trench (lined)	2005	No	No	Yes	Yes

Processing part of facility**CWM&TF**

The following shows processing status for waste classes and SRS.

Waste Class	Actual	Planned
VLLW	No	No
LLW	No	No
ILW	No	No
HLW	No	No

Type:	Treatment, Conditioning
Year opened:	1997